

NOTICE TO MARINERS

No29 – 2021

PORT OF LIVERPOOL

REPAIRS TO GLADSTONE LOCK EAST COPING

NOTICE IS HEREBY GIVEN that repairs to the east-side coping at Gladstone Lock have progressed to a point that requires installation of temporary shuttering.

Accordingly, and with immediate effect, vessels that send moorings ashore in Gladstone Lock must come alongside the west-side of the lock, unless directed to the contrary by the Dockmaster.

Vessels that do not send moorings ashore when in Gladstone Lock may, subject to the Dockmaster's direction, come alongside the east-side of the lock, provided that these vessels remain clear of the two areas under repair.

When the shuttering is in place, fenders approximately 30cm deep will be positioned on the east-side lock wall either side of the shuttering.