



## **NOTICE TO MARINERS**

**No 03/18**

### **SAFE SPEED**

Mariners are advised to exercise caution at all times and proceed at a safe speed in order to avoid risk of damage caused by wash or displacement. Recommended safe speed limits with Clydeport areas are:

Cumbræ Elbow Light to Cloch Point	19 knots
Cloch Point to Erskine Bridge, including Holy Loch	12 knots
Erskine Bridge to Albert Bridge	8 knots

Particular vigilance should be exercised when passing harbours, piers, moorings, beaches, recreational activities and any other areas involving property or persons.

Owners and operators of high speed RIB's and PWC should be particularly vigilant regarding their craft's characteristics/speed and the wash that can be created. Such craft should be operated in a courteous manner with consideration being given to other port users.

This notice applies to all vessels navigating within the jurisdiction of Clydeport Operations Ltd.