

NOTICE TO MARINERS

№3 - 2019

HEYSHAM HARBOUR

CHANGE OF CHARACTERISTIC OF THE LEADING LIGHTS

NOTICE IS HEREBY GIVEN that owing to technical reasons, the flash characteristic of the two red leading lights in the shape of Λ has been changed as follows:

Previous Characteristic: Ripple flashing from the bottom up

Amended Characteristic: Flashing

All other characteristics of the leading lights remain unaltered.

Mariners should update their copies of relevant publications accordingly.