

No. 24 – 2019

CHANGES TO NAVIGATION MARKS

1. Notice is hereby given that the following change has been made to navigation marks within the Medway and adjacent creeks.
2. The following Navigation Marks have been discontinued:
 - Aid: N05625 Rainham Creek Inner Can Buoy
 - Type, Character: Unlighted Buoy | Can R
 - Position - Latitude : 051 ° 22.929 N
 - Longitude: 000 ° 36.623 E
 - Datum: WGS84 Location: River Medway - Rainham Creek
 - Aid: N05624 Rainham Creek Outer Can Buoy
 - Type, Character: Unlighted Buoy | Can R
 - Position - Latitude : 051 ° 23.006 N
 - Longitude: 000 ° 36.789 E
 - Datum: WGS84 Location: River Medway - Rainham Creek
3. Further information may be obtained from Medway VTS on VHF Channel 74 call sign "Medway VTS" or direct via telephone on 0151 649 6148.
4. Admiralty Charts Nos. 1834, 2482 refer.

Marine Operations Department
Peel Ports London Medway

22nd August 2019