

# NOTICE TO MARINERS

## №34 – 2021

### HARBOUR AND PORT OF MANCHESTER

#### WEAVER SWINGING BASIN

NOTICE IS HEREBY GIVEN that it has been observed that the buoys demarking the Weaver swinging basin are out of position.

Whilst this matter is investigated and, if necessary, the buoys are repositioned, vessels proceeding above Ince Oil Berth bound for locations downstream of Runcorn Bend will be limited to swinging at the entrance to Runcorn Docks.

Under normal circumstances, vessels not exceeding 125 m in length overall can be swung at the entrance to Runcorn Docks.

A further Notice to Mariners will be issued when this matter is resolved.