

NOTICE TO MARINERS

№ 2 – 2025

HEYSHAM HARBOUR

LINKSPAN № 1

NOTICE IS HEREBY GIVEN that to enable repairs to the bank seat, Linkspan №1 has been uncoupled from its shoreside connections and is now fully afloat and moored alongside №1 berth approximately 110m seaward of its normal position. Fixed white lights mark the outboard side of the seaward end of the linkspan. Furthermore, the support craft *Ariel* will be in attendance to tend the linkspan's moorings.

Vessels manoeuvring within the Harbour, particularly those arriving at or departing from Linkspan №2, must be mindful of the effects of propeller wash and interaction on Linkspan №1 and its moorings.

It is anticipated that Linkspan №1 will remain in this temporary position for at least 10 days. A further Notice will be issued when it is returned to its normal position.

Notice to Mariners №7/2024 has been withdrawn.