

Any vessel wishing to conduct Hot Works at anchor or alongside a Clydeport Terminal must submit requests via online application. Vessels at a non-Clydeport berth are expected to follow the berth operator's procedures.

For each request, the following must be submitted:

- Risk Assessment
- Completed Permit to Work
- Gas Free Certificate where applicable

Any requests submitted without the above information will not be authorised.

Hot Works MAY NOT commence until an email notification confirming that the request has been authorised is received.

Applications may be submitted via the following link which is available on the Peel Ports Group website <https://app.youform.com/forms/hqdnxqqj>

All requests will be charged in line with Port Charges as published on the Peel Ports Group website.

Any queries regarding this procedure should be directed to [clydemarinemanagers@peelports.com](mailto:clydemarinemanagers@peelports.com)

---