



NOTICE TO MARINERS

No 19/18

RIVER AND FIRTH OF CLYDE – NAVIGATIONAL AIDS BUOY INSPECTION

Charts 1867, 1906, 1907, 1994, 2007, 2126, 2131, 2220, 2221, 2383

Mariners are advised that the MV CAMERON continues to carry out buoy refurbishments and inspections in the River and Firth of Clyde. These operations are scheduled to continue for a period of approximately 4-5 weeks.



The buoy refurbishment and inspections will be on the following Navigational Buoys:

Buoy Station: Refurbishment	
Skelmorlie C/L	Finnart No.3
No.31 Gantocks	Finnart No.4
Skelmorlie Channel D	River No.1
Skelmorlie Channel F	River No.4
Skelmorlie Channel I	River No.8
No.41 Ardmaliesh Point	River No.12
Dunoon Bank SE	River No.14
Kilcreggan Channel No.1	River No.29
Kilcreggan Channel No.2	River No.36



Buoy Station: Inspection			
River No.3	River No.30	Cardross	Clydeholm
River No.5	River No.32	River No.52	Port Glasgow
River No.7	River No.34	River No.70	Garvel Basin
River No.9	River No.40	River No.72	Captayannis
River No.13	River No.42	River No.74	Skelmorlie M
River No.16	River No.43	River No.76	Skelmorlie O
River No.17	River No.45	River No.78	No.36 Bogany Pt
River No.20	River No.46	RD1	Ardlamont Pt
River No.21	River No.47	RD2	Portavadie
River No.24	River No.48	RD3	
River No.28	River No.52	Yoker North	

As the MV CAMERON may be restricted in her ability to manoeuvre during the swap over and inspection operations, Mariners are asked to navigate with caution and give the vessel a wide berth. Estuary Radio and the CAMERON may be contacted on VHF 12. Estuary Radio can also be contacted on ☎ 0151 949 6651.