

NOTICE TO MARINERS No 28/24

FIRTH OF CLYDE AND RIVER CLYDE

NAVIGATIONAL AIDS

Mariners are advised, that following a review of Aids to Navigation, the following changes have been identified. Work to complete these changes will be completed by approximately mid-April 2024.

Chart	Location	Description of Change
2007 Plan C	Renfrew Lobnitz West Quay	Discontinuation of Starboard Lateral Mark
1867 Plan C	Hunterston Channel – Hun 5	Discontinuation of Starboard Channel Marker Buoy
1906	Kyles of Bute No 47 Ardlamont Point	Move buoy to 55°49.41'N 005°11.95'W around 15m contour and change to South Cardinal Mark
2126	Girvan Maidenhead Bay	Discontinuation of Special Mark Buoy
2383	Skipness Bay No 51	Move buoy to 55°45.52'N 005°20.00'W and change to South Cardinal Mark

In addition, the following AtoN will be attended as part of the planned routine inspection and maintenance programme:

Name	Name
Strone Point	River Clyde No.1
Gantock	River Clyde No.21
Toward Bank	River Clyde No.36
Burnt Islands Beere Rock	River Clyde No.72
Burnt Islands Creyke Rock	River Clyde No.74
Gulnare Rock	River Clyde No.76
Sgeir Scalag Shoal	River Clyde No.78
Ashton (Centreline)	Rubh A' Bhodaich
Burnt Islands Eilean Buidhe	Skelmorlie CL Safewater mark
Burnt Islands Eilean Fraoich	1 Rothesay Dock (West)
Burnt Islands Eilean Mor	2 Rothesay Dock (Centre)
Carry Point	3 Rothesay Dock (East)
Garvel Basin	The Patch Rosneath
Hunterston Farlie Patch	Clydeholm
Hunterston Jetty Inner	Eagle Rock
Hunterston No. 1	Ardrossan Inner Harbour
Hunterston No. 10	Portachur Spit No.38
Hunterston No. 11	Portavadie Lower Loch Fyne
Hunterston No. 12	River Clyde No.17
Hunterston No. 13	River Clyde No.2
Hunterston No. 14	River Clyde No.25
Hunterston No.3	River Clyde No.33
Hunterston No.7	River Clyde No.37
Hunterston No.8	River Clyde No.39

Hunterston No.9	Skelmorlie Bank No.32
Kilcreggan No. 1	Warden Bank
Portachur	West Crinan

MV Cameron will carry out this work and will maintain a listening watch on VHF Ch12 throughout. The vessel may be limited in ability to manoeuvre during operational periods and mariners are requested to navigate with caution.

MV CAMERON

