

Mariners are advised that a large anchor has been lost in Brodick Bay. The vessel has provided the approximate position of: 55° 35.291 N 005° 06.687 W

Vessels should avoid anchoring in the reported position. A hydrographic survey is planned to establish the exact location of the anchor.