

STANDING NOTICE TO MARINERS No 02 PILOT EMBARKATION PROCEDURES – COVID-19

Following the outbreak of the coronavirus COVID-19 the UK Department for Transport in consultation with Public Health England, has issued updates on the spread of the virus and guidelines https://www.gov.uk/coronavirus. Further advice for Scotland has been published at https://www.gov.scot/coronavirus-covid-19/.

In support of those guidelines, the following Pilot Embarkation Additional Procedure has been developed in consultation with Clyde Pilots, for the embarkation of pilots and subsequent vessel transit. **This procedure applies to all vessels.**

Responsibility for carrying out the following Pilot Embarkation Additional Procedure rests with the vessel's Master assisted by the shipowner and local ship agent as appropriate.

Agents are requested to make bookings for pilots in good time to allow allocation of pilots to be made in the most economical manner.

Clydeport are taking measures to protect Pilots and ensure they are healthy and free of any illness before they board your ship and it is expected that ships are taking suitable precautions to ensure the health of Clyde Pilots.

Pilot Embarkation Special Procedure

- All vessels must have submitted the required Maritime Declaration of Health (MDH) to the local
 Port Heath Authority (if there are any changes to the health status of the vessel while within port
 limits throughout the duration of the vessels stay then this must be declared immediately to Port
 Health and Clydeport LPS 'Estuary Radio' on VHF12);
- For vessels arriving via Port Limits Clydeport LPS will ask for confirmation that MDH has been submitted and that there has been no change since;
- Prior to the Pilot boat coming alongside a further advisory to the Pilot, via VHF radio, on the health status of all persons on board is to be made. This confirmation is in addition to the above;
- Immediately prior to pilot embarkation, all surfaces and equipment in the wheelhouse, or on the bridge wings, that the pilot may touch must be cleaned with a suitable cleaning solution;
- Where possible, the route from the embarkation point to the wheelhouse should be via the open deck, as opposed to within enclosed spaces, and be clear of ventilation unit exhausts. As far as it would not prejudice the normal operation of the vessel, non-essential crew and passengers should be kept clear of this route prior to and during pilot embarkation. One-person only to escort the Pilot to the bridge. Pilots should only be in areas of the ship essential for their work.
- The Pilot will not greet any shipboard personnel with the customary handshake.
- The wheelhouse, where possible, should remain well ventilated via the opening of external doors
 or windows. If this is not practicable, owing to the design of the vessel, its systems or prevailing
 conditions, all ventilation units on board the vessel should be adjusted to supply outside air only
 and air re-circulation must not take place.
- The wheelhouse must be cleared of all crew not essential to the navigation of the vessel.
- The Pilot will not sign onboard documentation; the pilot's signature being replaced by a crew member recording the pilot's name on the documentation in lieu of the signature. The pilot will apply a corresponding procedure for the Master's signature on the pilot line.

Version 3 01/01/22



- Unless necessary for the safety of the pilot (ie during the embarkation process), crew or vessel, the pilot and crew should remain at least 2m apart.
- Where facilities to wash hands are not available, hand sanitiser should be provided.
- Similar precautions must be taken during disembarkation of the pilot either ashore or to the pilot launch.

Pilots will wear PPE as defined by National Guidance advised through Public Health Scotland: https://publichealthscotland.scot/our-areas-of-work/covid-19/covid-19-health-protection-guidance/guidance-for-non-healthcare-settings/

If any vessel is not able to comply with the requirements of this notice they are required to notify Estuary Radio on VHF Ch12 when making their report prior to entering the Port Limits, as shown on Admiralty Chart 2126 and noted in Admiralty List of Radio Signals Volume 6. Failure to comply with this notice may result in your pilot being cancelled or your vessel delayed.

If there is a report of a suspected case of COVID-19 on board a vessel, the pilot embarkation will be cancelled pending the receipt of specific guidance from the Port Health Authority.

Furthermore, Masters of vessels are advised that if the pilot assigned to the vessel reports any symptoms of COVID-19 prior to embarkation, reasonable endeavours will be made to assign a replacement pilot in time for the vessel's planned transit. However, depending on the prevailing demand for pilots, this may not be possible. In which case, the booking will be cancelled and the local agent required to re-submit the booking for a later time.

For further information contact Estuary Radio 20151-949 6651 or VHF 12.

Version 3 01/01/22