



**NOTICE TO MARINERS No 42/24  
FIRTH OF CLYDE – HUNTERSTON  
DISCONTINUATION OF AtoN**

**Chart 1907**

Mariners are advised that Hunterston No.5 Buoy has been removed from its position 55°45.873'N 004°52.522'W and discontinued.