

Mariners are advised that an unlicensed mooring has been identified in Brodick Bay, in position 55°34.725N 05°08.614W. It has two small floating buoys attached and is approx. 50m in length.



Investigations are ongoing to establish the ownership of this mooring. It is adjacent to the visitor moorings and licensed mooring association areas. Mariners should navigate with additional caution in this location.

