

NOTICE TO MARINERS

№13 – 2022

PORT OF LIVERPOOL

DAMAGED FENDER AT HORNBY SWING BRIDGE

NOTICE IS HEREBY GIVEN that the large, timber fender (which had been damaged) on the south-west approach to the Hornby Swing Bridge has been removed.

Replacement fendering has been deployed as illustrated below.



Notice to Mariners №12/2022 is withdrawn.