

30.00m

25.00m

30.00m

25.00m

SANDON DOCK
RIVER ENTRANCE
(DISUSED)

NO ACCESS
THROUGH
PASSAGE

Please note:
Wellington Dock is no longer a working dock
and is now filled in.

Please note:
Bramley Moore Dock is no longer a working dock
and is now filled in.

Milhouse Rocks

Victoria Tower

Salisbury
Pier Head

SALISBURY DOCK

SW HUSKISSON NO 1

HUSKISSON DOCK BRANCH NO 1

SE HUSKISSON NO 1

Sill level 2.57m
below Chart Datum (75)

Sill level 1.67m
above Chart
Datum (75)

Sill level 1.82m above Chart Datum (75)

BRAMLEY MOORE DOCK

Obstn

Obstn

Obstn

Obstn

Sill level 1.82m above Chart Datum (75)

Obstn

Obstn



MERSEY DOCKS AND
HARBOUR COMPANY LTD

Gary Doyle
Group Harbour Master

Liverpool Docks

LPD007_1_2025_001
Sandon Half Tide
Dock

DEPTHS
Depths are in metres and are reduced to chart datum
being 4.93m below Ordnance Datum (Newlyn),
which is approximately the level of
Lowest Astronomical Tide.

HEIGHTS
Heights are in metres. Underlined
figures show heights above Chart Datum.

Depth (M)




POSITIONS
Positions are referred to OSGB36 National Grid Datum.

UKHO & NTMS
When using this chart please refer to UKHO Admiralty
Publications and also local Notice to Mariners and
Navigational Warnings.

TOPOGRAPHY
The shore features on this
chart are based largely on
Ordnance Survey digital
mapping data with permission of
HMSO. © Crown Copyright 2025.
Peel Licence Number 100018033.

FLATS & SANDBANKS
CAUTION OWING TO FREQUENT CHANGES
IN DEPTHS AND POSITIONS OF FLATS AND
SANDBANKS THIS CHART SHOULD BE USED
WITH CAUTION.



Surveyed by: NM
Processed by: AJD
Checked by: RK
Surveyed: 7th May 2025
Issued: 9th May 2025
Vessel: Fitzroy

SCALE 1:1250 at A1

