

HORNBY PASSAGE
Sill level 2.55m below CD (75)

HORNBY PASSAGE

Cable Area
Dredging
Prohibited

HORNBY DOCK

Gladstone River Entrance Lock
(Please see latest chart for the Lock)

Gladstone River Entrance
Lock Sill Level 5.6m
below chart datum (1975)



MERSEY DOCKS AND HARBOUR COMPANY LTD
Captain Susan Cloggie-Holden MNM
Group Harbour Master
Liverpool Docks
LPD002_2_2026_008
Gladstone Lock

DEPTHS
Depths are in metres and are reduced to chart datum being 4.93m below Ordnance Datum (Newlyn), which is approximately the level of Lowest Astronomical Tide.


HEIGHTS
Heights are in metres. Underlined figures show heights above Chart Datum.

POSITIONS
Positions are referred to OSGB36 National Grid Datum.


UKHO & NTMS
When using this chart please refer to UKHO Admiralty Publications and also local Notice to Mariners and Navigational Warnings.

TOPOGRAPHY
The shore features on this chart are based largely on Ordnance Survey digital mapping data with permission of HMSO. © Crown Copyright 2026. Peel Licence Number 100018033.

FLATS & SANDBANKS
CAUTION OWING TO FREQUENT CHANGES IN DEPTHS AND POSITIONS OF FLATS AND SANDBANKS THIS CHART SHOULD BE USED WITH CAUTION.



Vessel:	Porth Wen
Surveyed by:	VO
Processed by:	NM
Checked by:	NM
Surveyed:	5th June 2026
Issued:	5th June 2026



SCALE 1:500 at A1

