




300m

250m

300m

250m

SW HUSKISSON NO 1

SE HUSKISSON NO 1

HUSKISSON DOCK BRANCH NO 1

SANDON
HALF-TIDE
DOCK

Sill level 2.57m
below Chart Datum (75)

WELLINGTON DOCK

Please note:
Wellington Dock is no longer a working dock
and is now filled in.

Sill level 1.67m
above Chart
Datum (75)

Sill level 1.82m above Chart Datum (75)

BRAMLEY MOORE DOCK

Please note:
Bramley Moore Dock is no longer a working dock
and is now filled in.

Sill level 1.82m above Chart Datum (75)

NO ACCESS
THROUGH
PASSAGE

SANDON DOCK
RIVER ENTRANCE
(DISUSED)



MERSEY DOCKS AND
HARBOUR COMPANY LTD

Captain Susan Cloggie-Holden MNM
Group Harbour Master


Liverpool Docks

LPD007_1_2026_002

Sandon Half Tide
Dock

DEPTHS
Depths are in metres and are reduced to chart datum
being 4.93m below Ordnance Datum (Newlyn),
which is approximately the level of
Lowest Astronomical Tide.

HEIGHTS
Heights are in metres. Underlined
figures show heights above Chart Datum.




POSITIONS
Positions are referred to OSGB36 National Grid Datum.

UKHO & NTMS
When using this chart please refer to UKHO Admiralty
Publications and also local Notice to Mariners and
Navigational Warnings.


TOPOGRAPHY
The shore features on this
chart are based largely on
Ordnance Survey digital
mapping data with permission of
HMSO. © Crown Copyright 2026.
Peel Licence Number 100018033.

FLATS & SANDBANKS
CAUTION OWING TO FREQUENT CHANGES
IN DEPTHS AND POSITIONS OF FLATS AND
SANDBANKS THIS CHART SHOULD BE USED
WITH CAUTION.



Surveyed by:	WLH
Processed by:	WLH
Checked by:	WLH
Surveyed:	22nd October 2026
Issued:	23rd October 2026
Vessel:	Royal Charter

SCALE 1:1250 at A1



300m