



**MERSEY DOCKS AND
HARBOUR COMPANY LTD**
Captain Susan Cloggie-Holden MNM
Group Harbour Master

River Mersey
LPR001_3_2026_011C
Langton River
Entrance

DEPTHS
Depths are in metres and are reduced to chart datum
being 4.93m below Ordnance Datum (Newlyn),
which is approximately the level of
Lowest Astronomical Tide.

HEIGHTS
Heights are in metres. Underlined
figures show heights above Chart Datum.




POSITIONS
Positions are referred to OSGB36 National Grid Datum.

UKHO & NTMS
When using this chart please refer to UKHO Admiralty
Publications and also local Notice to Mariners and
Navigational Warnings.

Vessel:	Porth Wen
Surveyed by:	VO
Processed by:	VO
Checked by:	RK
Surveyed:	28th July 2026
Issued:	29th July 2026
Lock Surveyed:	24th July 2026

TOPOGRAPHY
The shore features on this
chart are based largely on
Ordnance Survey digital
mapping data with permission of
HMSO. © Crown Copyright 2026.
Peel Licence Number 100018033.

FLATS & SANDBANKS
**CAUTION OWING TO FREQUENT CHANGES
IN DEPTHS AND POSITIONS OF FLATS AND
SANDBANKS THIS CHART SHOULD BE USED
WITH CAUTION.**



NOTE OBSTRUCTIONS IN THE VICINITY OF THE LOCK ENTRANCE/BULLNOSE
Bathymetric data shows various historically
known long standing seabed structures/artefacts
thought possibly to be part of the original
River Entrance construction
which are now, in the interest of navigation,
being shown as obstructions

